

Baustatus BT-Grundsicherung Herder

	<p>Fluransicht</p>
	<p>Fluransicht mitte</p>
	<p>Raumdurchbruch Fluchttür</p>

Baustatus BT-Grundsicherung Herder

 A photograph showing the interior of a vaulted ceiling during renovation. Scaffolding is erected around the structure, and the wooden framework of the ceiling is visible through the arch.	<p>Entdeckung - Oberlicht</p>
 A photograph of a room with a chalkboard on the left wall. The chalkboard has a drawing of a face and the text 'Kau los geht weip.' written on it. An open doorway in the center leads to another room.	<p>Raumdurchbrüche - Bereich Kunst</p>
 A photograph of a hallway with a green door leaning against the wall. A doorway in the background leads to another room. A spherical pendant light hangs from the ceiling.	<p>Brandsicherung Seitenflügel</p>


Baustatus BT-Grundsicherung Herder



Flurbereich Brandschutztüren



Kann passieren...



Kabelverlegung

Baustatus BT-Grundsicherung Herder



Farbrecherche

Brandsicherung Seitenflügel

Verteilerkasten - Innenansicht

Baustatus BT-Grundsicherung Herder



Flurbereich, 1. Etage



Flurbereich Erdgeschoss



Deckenbereich nach Kabelzug

Baustatus BT-Grundsicherung Herder

	Seitenflügel Erdgeschoss
	Zukünftiger Schülerbereich
	Sanierung Kellergeschoss

Baustatus BT-Grundsicherung Herder



Mängelbeseitigung,
entdeckt bei
Befundaufnahme



Sanierung Turnhalle



Aula - fast unberührt
(nur Arbeiten im
Deckenbereich)